






# Diversos Materiais (Manómetros)

Artigos 1040 a 1054



**MANOMETROS**

	CODIGO	DIAMETRO	ESCALA	CAIXA				PN	QUANT. Cx.		
									PEQ	GRANDE	
 <b>ART. 09.01040</b>	<b>ART. 1040 - MANOMETROS HORIZONTAIS (AXIAIS) CAIXA ABS</b>										
	09.01040.006	53	0-06	ABS							
	09.01040.010	53	0-10	ABS							
	09.01040.016	53	0-16	ABS							
	09.01040.025	53	0-25	ABS							
 <b>ART. 09.01045</b>	<b>ART. 1045 - MANOMETROS VERTICAIS (RADIAIS) CAIXA ABS</b>										
	09.01045.006	53	0-06	ABS							
	09.01045.010	53	0-10	ABS							
	09.01045.016	53	0-16	ABS							
	09.01045.025	53	0-25	ABS							
 <b>ART. 09.01050</b>	<b>ART. 1050 - MANOMETROS GLICERINA VERTICAIS (RADIAIS) CAIXA INOX</b>										
	09.01050.002	63	0-02,5	INOX							
	09.01050.004	63	0-04	INOX							
	09.01050.006	63	0-06	INOX							
	09.01050.010	63	0-10	INOX							
	09.01050.016	63	0-16	INOX							
	09.01050.025	63	0-25	INOX							
	09.01050.060	63	0-60	INOX							
09.01050.100	63	0-100	INOX								
 <b>ART. 09.01052</b>	<b>ART. 1052 - MANOMETROS GLICERINA VERTICAIS (RADIAIS) TOTALMENTE INOX</b>										
	09.01052.006	100	0-06	INOX							
	09.01052.010	100	0-10	INOX							
	09.01052.016	100	0-16	INOX							
	09.01052.025	100	0-25	INOX							
	09.01052.060	100	0-60	INOX							
 <b>ART. 09.01054</b>	<b>ART. 1054 - MANOMETROS GLICERINA HORIZONTAIS (AXIAIS) TOTALMENTE INOX</b>										
	09.01054.006	63	0-06	INOX							
	09.01054.010	63	0-10	INOX							
	09.01054.016	63	0-16	INOX							
	09.01054.025	63	0-25	INOX							
	09.01054.060	63	0-60	INOX							
09.01054.100	63	0-100	INOX								

ESTA TABELA PODE SER ALTERADA SEM AVISO PRÉVIO E ANULA TODAS AS ANTERIORES.  
Os componentes e valores poderão variar de acordo com o desenvolvimento e melhoria dos produtos.